

# DATACOM



## DmOS

DATACOM OPERATING SYSTEM

Version 9.4.0

### RELEASE NOTES

204.4295.70 - December 19, 2023

## Contacts

### Technical Support

Datacom has available a support portal - DmSupport, to help the customers in use and config of our equipment.

Access to the DmSupport can be made through link: <https://supportcenter.datacom.com.br>

In this site the following are available: firmwares, technical datasheets, config guide, MIBs and manuals for download. In addition, it allows opening of calls for assistance with our technical team.

Telephone Number: **+55 51 3933-3122**

We would like to highlight that our assistance through telephone support is available from Monday through Friday from 08:00 AM through 05:30 PM.

**Important:** For support assistance 24x7, please request a quotation to our sales department.

### General Information

For any other additional information, please visit the <https://www.datacom.com.br/en> or call:

**DATAKOM**

**Rua América, 1000**

**92990-000 - Eldorado do Sul - RS - Brazil**

**+55 51 3933-3000**

## Product Documentation

This document is part of a set of documents prepared to provide all necessary information about DATACOM products.

### Software Platform

- **Quick Configuration Guide** - Provides instructions on how to set functionalities in a quick manner in the equipment
- **Troubleshooting Guide** - Provides instructions on how to analyze, identify and solve problems with the product
- **Command Reference** - Provides all the commands related to the product
- **Release Notes** - Provides instructions on the new functionalities, identified defects and compatibilities between Software and Hardware

### Hardware Platform

- **Datasheet** - Provides the Hardware and Software technical characteristics of product
- **Installation Guide** - Provides instructions on the procedures covering product installation

The availability of some documents can vary depending on the type of product.

Access <https://supportcenter.datacom.com.br> to locate the related documents or contact the Technical Support for additional information.



# Introduction to the document

## About this Document

This report provides information regarding a new software release version for DmOS product. The Release Notes also intends to inform relevant changes that have occurred in software, hardware and documentation.

It is assumed the reader is familiar with network protocols concepts and has previous knowledge about DmOS products.

## Audience

This document is intended for Network Administrators, Engineers and any other qualified service personnel who are responsible for configuring and maintaining networks deployed with DmOS.

## Text Convention

This report uses these text conventions to convey instructions and information:

Convention	Description
Hyperlink	Internet site or an e-mail address. It is also applied to indicate a local link inside the document itself (e.g. a chapter).
Terminal	System commands and screen outputs.
<i>Object</i>	Indicates a reference to something. Used to emphasize this referenced object.
<b>Menu &gt; Path</b>	GUI (Graphic User Interface) menu paths.
[Key]	Keyboard buttons.

## Table of Contents

<b>Contacts</b>	<b>2</b>
<b>Product Documentation</b>	<b>3</b>
<b>Introduction to the document</b>	<b>4</b>
<b>1 Important Notes</b>	<b>6</b>
<b>2 Hardware and Software Compatibility</b>	<b>7</b>
2.1 Released Software . . . . .	7
2.2 Product Compatibility . . . . .	7
2.3 Compatibility Between Software Versions . . . . .	9
2.4 Compatibility of Electrical Modules . . . . .	15
2.5 Compatibility of Electrical Cables . . . . .	16
2.6 SSL Encryption Compatibility . . . . .	16
<b>3 New Features and Enhancements</b>	<b>18</b>
3.1 New Features . . . . .	18
3.2 Enhancements . . . . .	18
3.3 Changes in protocols management . . . . .	18
<b>4 Solved Issues and Restrictions</b>	<b>19</b>
4.1 Solved Issues . . . . .	19
4.2 Restrictions . . . . .	20
<b>5 Document Versions</b>	<b>42</b>
5.1 Software Platform . . . . .	42
5.2 Hardware Platform . . . . .	42
<b>Legal Note</b>	<b>43</b>
<b>Warranty</b>	<b>43</b>

## 1 Important Notes

The table below provides important notes that should be observed when using the product.

Note	Product
Unable to load configuration XML files with dot1q that were saved DmOS versions before 8.0.0. Text mode config files works perfectly. In case you need to load an xml file that contains vlan configuration, you will need edit the xml file changing from <i>http://tail-f.com/ns/dmvlan-manager</i> to <i>urn:dmos:dmos-dot1q</i> .	All
Unable to load configuration XML files with lag that were saved DmOS versions before 9.2.0. Text mode config files works perfectly. In case you need to load an xml file that contains lag configuration, you will need edit the xml file changing from <i>http://tail-f.com/ns/lacp</i> to <i>urn:dmos:dmos-lag</i> .	All
Increasing the number of objects or decreasing the interval between SNMP requests might lead to management latency or SNMP errors.	All
DmOS devices support autocorrection for occurrences of data corruption in memory. There may be cases after power outages or swings where the system cannot perform data autocorrection and may cause loss of logs or configurations.	All
The memory can be allocated by internal processes due to successive link-flaps. After flap stop, the memory will return to initial state. It is recommended to use the Link-Flap-Detection feature in ethernet interfaces.	All
VPN configurations that use the default MTU size configuration before DmOS 3.0.0 must observe the change in the default value from 1500 to 9198, which may cause a configuration mismatch.	All
In version 9.0.0 or above it will not be possible to configure weak passwords for local database users. If there is a need to change the password configuration of the equipment, it will be necessary to change the configuration to a strong password, according to the requirements presented in the CLI on the equipment.	All
It is possible to update all ONUs in a PONLink simultaneously provided that all ONUs are model equivalent. If there are ONUs of different models in a PONLink, it is not recommended to use the "all" parameter in command request firmware onu install <image> interface gpon <id> .	DM461X
It is not recommended to configure the snmp real-time option for more than 128 ONUs. Large scale monitoring can cause performance impacts, such as an increase in ONU status update time. When using the DM461X products (OLT GPON) and operating near the maximum supported ONUs by the platform, it is recommended that the SNMP requests interval is no lower than 15 minutes.	DM461X

## 2 Hardware and Software Compatibility

This chapter lists hardware and software compatibility for this software release.

### 2.1 Released Software

This session presents the software release details:

Product	Release Version
DmOS	9.4.0



The downtime after upgrading to the 9.4.0 version on the DM4360, DM4370 and DM4370 SAT platforms will be longer if it is in a firmware version that has a oldest FPGA version.



**DmOS 5.0** is the LTS release (Long-Term Support) for platform **DM4610 OLT 8GPON+8GX+4GT+2XS** (P/N 800.5081.xx). The platform will still receive maintenance releases based on DmOS 5.0, if necessary, with bug fixes. However, there will be no updates with new features. Other OLTs will still receive new features and bug fixes.



**DmOS 5.2** is the LTS release (Long-Term Support) for platform **DM4775 32CX** (P/N 820.0014.00). The platform will still receive maintenance releases based on DmOS 5.2, if necessary, with bug fixes. However, there will be no updates with new features.



For scalability values per platform, check document DmOS – DmOS Datasheet.

### 2.2 Product Compatibility



To use management via DmView with the DmOS version 9.4.0 it is necessary to update DmView to version 11.2 or greater.

The table below shows the product compatibility matrix stating the **minimum** hardware version, minimum software version and the minimum version of DmView (management software).

Product	Hardware Version	Software Version	DmView Version
DM4050 24GT+6XS	800.5189.00	2.2.0	10.3
DM4050 24GX+6XS	800.5190.00	2.2.0	10.3
DM4170 24GX+4XS+2QX	800.5184.01	3.0.0	10.3
DM4170 24GX+12XS	800.5186.01	2.2.0	10.3
DM4250 24XS+2QX	800.5197.02	4.0.0	10.3
DM4270 24XS+2CX	800.5231.53 800.5231.60	4.7.0 8.2.0	10.3
DM4270 48XS+6CX	800.5213.53 800.5213.61 800.5304.61	4.9.0 8.0.4 8.0.4	10.3
DM4270 8XS+16VS+6CX	800.5313.62	9.2.0	10.3
DM4360 4GT+4GX	800.5259.50 800.5259.70 800.5259.75	4.10.0 8.0.6 8.2.0	10.3
DM4370 4GT+4GX+4XS	800.5191.00 800.5191.70 800.5191.75	3.0.0 8.0.6 8.2.0	10.3
DM4370 4GT+4GX+4XS+SAT	800.5273.53 800.5273.70 800.5273.75	7.4.0 8.0.6 8.2.0	10.3
DM4380 12XS+3CX	800.5258.00 800.5258.60	5.0.0 8.2.0	10.3
DM4610 OLT 8GPON+8GX+4GT+2XS	800.5081.03	1.4.0	10.3
DM4610 OLT 4GPON+4GX+2XS (HW2)	800.5193.01	2.4.0	10.3
DM4610 OLT 8GPON+8GX+4GT+2XS (HW2)	800.5165.01	2.2.0	10.3
DM4611 OLT 4GPON+2GT+2XS	800.5283.51	6.2.0	10.3
DM4612 OLT 8GPON+2GT+2XS	800.5285.51	6.2.0	10.3
DM4615 OLT 16GPON+4GT+4XS	800.5198.01	4.2.0	10.3
DM4616 OLT 4XGS-PON+4XS	800.5298.51	9.0.0	11.3.0
DM4618 OLT 32GPON	800.5275.51	8.2.0	11.2
DM4770 16CX	800.5280.51	6.0.0	10.3



Product	Hardware Version	Software Version	DmView Version
DM4770 32CX	800.5255.52	5.8.0	10.3
DM4775 32CX	820.0015.00 820.0016.00	4.9.0	10.3
<b>DM4920</b>	<b>800.5299.51</b>	<b>9.4.0</b>	-



**Bold items - new hardware platform available in the current version of DmOS.**

## 2.3 Compatibility Between Software Versions

The tables below shows the compatibility matrix between firmware versions, including the notes for the firmware update process.

### Software Upgrade

For **DM4050** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions				Final Version
DM4050	2.2.0	2.2.2	3.0.4	4.6.2	5.2.0	9.4.0
DM4050	2.2.2	-	3.0.4	4.6.2	5.2.0	9.4.0
DM4050	3.0.4 or higher	-	-	4.6.2	5.2.0	9.4.0
DM4050	4.6.2 or higher	-	-	-	5.2.0	9.4.0
DM4050	5.2.0 or higher	-	-	-	-	9.4.0

For **DM4170** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions				Final Version
DM4170	2.2.0	2.2.2	3.0.4	4.6.2	5.2.0	9.4.0
DM4170	2.2.2	-	3.0.4	4.6.2	5.2.0	9.4.0
DM4170	3.0.4 or higher	-	-	4.6.2	5.2.0	9.4.0
DM4170	4.6.2 or higher	-	-	-	5.2.0	9.4.0
DM4170	5.2.0 or higher	-	-	-	-	9.4.0

For **DM4250** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions				Final Version
DM4250	4.0.0 or higher	4.6.2	5.2.0			9.4.0
DM4250	4.6.2 or higher	-	5.2.0			9.4.0
DM4250	5.2.0 or higher	-	-			9.4.0

For **DM4270 24XS+2CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions				Final Version
DM4270 24XS+2CX	4.7.0 or higher	5.2.0				9.4.0
DM4270 24XS+2CX	5.2.0 or higher	-				9.4.0

For **DM4270 48XS+6CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4270 48XS+6CX	4.9.0 or higher	5.2.0	9.4.0
DM4270 48XS+6CX	5.2.0 or higher	-	9.4.0

For **DM4270 8XS+16VS+6CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4270 8XS+16VS+6CX	9.2.0 or higher	-	9.4.0

For **DM4360** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4360	4.10.0 or higher	5.2.0	9.4.0
DM4360	5.2.0 or higher	-	9.4.0

For **DM4370 4GT+4GX+4XS** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions			Final Version
DM4370	3.0.0	3.0.4	4.6.2	5.2.0	9.4.0
DM4370	3.0.4 or higher	-	4.6.2	5.2.0	9.4.0
DM4370	4.6.2 or higher	-	-	5.2.0	9.4.0
DM4370	5.2.0 or higher	-	-	-	9.4.0

For **DM4370 4GT+4GX+4XS+SAT** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4370 SAT	7.4.0 or higher	-	9.4.0

For **DM4380** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4380	5.0.0 or higher	5.2.0	9.4.0
DM4380	5.0.0 or higher	-	9.4.0

For **DM4610 HW1** platform, the DmOS has the following compatibility matrix:

Platform	Initial Version	Mandatory Intermediate Versions				Final Version
DM4610 HW1	1.8.0 or lower	1.8.2	2.2.2	3.0.4	4.0.2	5.0.6
DM4610 HW1	1.8.2 to 2.0.4	-	2.2.2	3.0.4	4.0.2	5.0.6
DM4610 HW1	2.2.2 to 3.0.2	-	-	3.0.4	4.0.2	5.0.6
DM4610 HW1	3.0.4 to 4.0.0	-	-	-	4.0.2	5.0.6
DM4610 HW1	4.0.2 or higher	-	-	-	-	5.0.6

For **DM4610 HW2** platform, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions					Final Version
DM4610 HW2	1.8.0 or lower	1.8.2	2.2.2	3.0.4	4.0.2	5.2.0	9.4.0

Platform	Initial Version	Mandatory Intermediate Versions					Final Version
DM4610 HW2	1.8.2 to 2.0.4	-	2.2.2	3.0.4	4.0.2	5.2.0	9.4.0
DM4610 HW2	2.2.2 to 3.0.2	-	-	3.0.4	4.0.2	5.2.0	9.4.0
DM4610 HW2	3.0.4 to 4.0.0	-	-	-	4.0.2	5.2.0	9.4.0
DM4610 HW2	4.0.0 to 4.0.2	-	-	-	-	5.2.0	9.4.0
DM4610 HW2	5.2.0 or higher	-	-	-	-	-	9.4.0

For **DM4611 and DM4612** platforms, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions					Final Version
DM4611 and DM4612	6.0.0 or higher	-					9.4.0

For **DM4615** platform, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions					Final Version
DM4615	4.0.0 or higher	5.2.0					9.4.0
DM4615	5.2.0 or higher	-					9.4.0

For **DM4618** platform, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions					Final Version
DM4618	8.0.0 or higher	-					9.4.0

For **DM4770 16CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4770 16CX	6.0.0 or higher	-	9.4.0

For **DM4770 32CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4770 32CX	5.8.0 or higher	-	9.4.0

For **DM4775** platform, DmOS has the following compatibility matrix:

Platform	Initial Version	Mandatory Intermediate Versions	Final Version
DM4775	4.9.0 or higher	-	5.2.0

#### Notes

It is always recommend save the configuration before firmware update process. To save the configuration use the **save <archivo>** command.

In case of doubt, please call to Datacom technical support.

## Software Downgrade

#### Notes

From version 8.2.0 or later it is not possible to perform a firmware downgrade in DM4360, DM4370 and DM4370 SAT platforms to versions lower than 8.2.0. If this operation is performed you must contact Datacom's technical support.

**Notes**

There is no support to maintain current database in downgrade. When performing the downgrade, the previous database is restored and any configuration changes made after upgrade to version 4.x or higher will be lost in the downgrade process. In case of downgrade to version different from previous, the equipment will boot with factory configuration.

From version 2.4.0 it is only possible to perform firmware downgrade to version 2.0.0 or 2.2.2. Firmware downgrade to older versions is not allowed by the system.

## 2.4 Compatibility of Electrical Modules

The table below shows the matrix about electrical modules support (SFP Copper) by each product line and which version initiated its support. It's advised the use of **negotiation** on interfaces with copper SFPs.



The SFP Copper supported has **377.7000.00** Datacom code. Datacom does not guarantee compatibility with other modules. Contact us for more information.

Product Line	Software Version
DM4050	2.2.0
DM4170	2.2.0
DM4250	4.8.0
DM4270 24XS+2CX	4.8.0
DM4270 48XS+6CX	5.0.0 (forced only <sup>1</sup> )
DM4360	4.10.0
DM4370	3.0.0
DM4380	5.0.0
DM4610	2.2.0
DM4611	6.2.0
DM4612	6.2.0
DM4615	4.2.0
DM4616	9.0.0
DM4618 OLT 32GPON	8.0.0
DM4770 16CX	6.0.0 (forced only <sup>1</sup> )

Product Line	Software Version
DM4770 32CX	5.8.0
DM4775	4.9.0
DM4920	Not available



<sup>1</sup> **DM4270 48XS+6CX** and **DM4770 16CX** don't support negotiation on ten-gigabit interfaces and twenty-five-gigabit interfaces, but it's possible to make use of copper modules setting the interface to forced mode (no negotiation). The presence of a copper module makes the interface negotiate with the link partner advertising 1 Gbps speed only, with no support for pause frames or lower speeds, regardless of its current configuration. When operating in this mode, a link down status may take up to 10 seconds to be reported.

## 2.5 Compatibility of Electrical Cables

The table below shows the electrical cables support matrix recommended by Datacom.



The use of non recommended cables can cause performance problems.

Code	Description
710.0384.00	DAC Passive Cable 40GbE QSFP+ to QSFP+ (1m)
710.0391.00	DAC Passive Cable 40GbE QSFP+ to QSFP+ (3m)
710.0395.00	DAC Passive Cable 100GbE QSFP28 to QSFP28 (1m)
710.0396.00	DAC Passive Cable 100GbE QSFP28 to QSFP28 (3m)

## 2.6 SSL Encryption Compatibility

The table below lists the OpenSSL versions for each software version and which version initiated its support.

Software Version	OpenSSL Version
1.4.2	1.0.1f
1.10.0	1.0.2j
1.12.0	1.0.2k
2.4.0	1.0.2l



Software Version	OpenSSL Version
4.0.0	1.0.2o
4.9.0	1.0.2r
5.0.0	1.0.2t
8.0.0	1.0.2u

## 3 New Features and Enhancements

This chapter lists new features, enhancements and changes in commands introduced in this release.

### 3.1 New Features

Feature	Description	ID
<b>DmOS</b>	Support to DM4920 DWDM platform.	F2024
<b>GPON</b>	Support to <i>native downstream-mode inverse-of-upstream</i> command in auto-provisioning configuration.	F1501
<b>GPON</b>	Support to <i>load default-xgspon-profiles</i> command for bridge or router ONU.	F2171
<b>SNMP</b>	Support to SNMP object onuCountingIfMIB <b>OID: 1.3.6.1.4.1.3709.3.6.18</b> to query the total number of ONUs, total number of non-provisioned ONUs, total number of Up ONUs and total number of Down ONUs.	F845
<b>SNMP</b>	Support to SNMP object ipAdEntIfIndex <b>OID: 1.3.6.1.2.1.4.20.1.2</b> to consult IP addresses configured on the equipment.	F2203

### 3.2 Enhancements

Feature	Description	ID
<b>Admin Password</b>	Improvement in the password recovery process for the <b>admin</b> user.	F2015
<b>LAG</b>	Support to LAG interface status logging.	F1816
<b>System</b>	The nbase-stub process, responsible for network protocols, is not recovered correctly in the event of death, meaning that the next configuration changes will not be applied correctly. From version 9.4.0 or later, the equipment will restart automatically if this process dies.	191380
<b>System</b>	Temperature sensor driver update for model DM4250 24XS+2QX.	187396
<b>Transceivers</b>	Enhancement of the parameterization of GPON modules GPON 374.0231.00, 374.0204. 00, 374.0197.00.	180348

### 3.3 Changes in protocols management

Feature	Description	ID
-	-	-

## 4 Solved Issues and Restrictions

This section lists solved issues and known restrictions for this software release.

- **Solved Issues:** Fixed bugs in this version.
- **Restrictions:** DmOS Software restrictions per hardware platforms.

### 4.1 Solved Issues

Feature	Description	ID	Affected Platforms
<b>DHCPv6</b>	DHCPv6 packets could be looped in VLANs with an associated L3 interface, which could cause CPU overload.	189788	DM4618
<b>DmView</b>	DmView can not backup the equipment configuration in text mode and also cannot display the running-config when using special characters in the <i>alias</i> config.	178239	All
<b>ECMP</b>	MPLS configuration (LDP/RSVP) in some cases causes ECMP to stop working for L3 prefixes that do not use MPLS.	169852	All
<b>GPON</b>	Excess DLF or Broadcast traffic downstream can cause the <b>Adapt Failure</b> alarm on the DM4618 Line Card, affecting the service of all clients connected to this Line Card.	189877	DM4618
<b>GPON</b>	Rx optical power of ONUs is not updated correctly after changes in fiber attenuation.	189238	DM4616
<b>GPON</b>	Fix of the MTU to 9000 bytes when the PON interface is configured in XGS-PON mode, when the PON interface is configured in GPON mode, the MTU will remain 2040 bytes. This MTU value is applied to the ONU's Ethernet interface.	187832	DM4616
<b>GPON</b>	For provisioning ONUs, the DM4616 could present lower performance than other OLTs.	186469	DM4616
<b>Interfaces</b>	It is not possible to configure 100G interfaces using Netconf or DmView.	188124	DM4770
<b>Interfaces</b>	Ten-gigabit Ethernet interfaces can present packet loss when used in 1G mode.	182761	DM4270 48XS+6CX
<b>LAG</b>	LAG interfaces connected to standby MC LAG shows active instead of inactive state in <i>show link-aggregation interfaces</i> command.	184273	All
<b>L2VPN</b>	When executing the <i>show mpls l2vpn hardware brief</i> command, core-dump is generated in the vpn-app process due to inconsistencies in the configuration of any L2VPN configured on the device.	185210	All

Feature	Description	ID	Affected Platforms
<b>L2VPN</b>	After oscillations in the MPLS infrastructure network, L2VPNs remained functional, but could display inconsistent statuses such as DOWN or GOING-DOWN.	185924	All
<b>MPLS</b>	Entry in the MPLS forwarding-table eventually remained in the POP state, affecting traffic.	179932	All
<b>RSVP</b>	MTU configuration in L3 interfaces <i>ip-mtu</i> does not reflect in the RSVP protocol.	163335	All
<b>SNMP</b>	Changing the IP on the interface used to configure the SNMP agent listen causes the process to restart every 5 seconds, affecting the equipment's uptime information.	160960	All
<b>QoS</b>	Removing and adding QoS Policer instances causes bandwidth profiles to be shared.	184174	All
<b>Transceivers</b>	Failure in the digital diagnostics information of some GPON transceivers.	171104	DM461x
<b>Transceivers</b>	RX-LOS status of GPON transceivers is not supported.	185641	DM461x

## 4.2 Restrictions

Feature	Description	ID	Affected Platforms
<b>AAA</b>	During the creation of a local user you need to enter the password between double quotes ( " " ) if you use the character ! on the password. Alternatively it is possible to use the configuration assistant, activating it with the command without providing the password, after <i>enter</i> the system will request the password and in this step, the special characters are accepted without the need to use quotation marks.	177838	All
<b>ACL</b>	There is no support to access list in service-ports, only in PON links.	-	All
<b>ACL</b>	Broadcast and DLF traffic will be forwarded to CPU even when there is an ACL blocking it.	122376	All
<b>ACL</b>	ACL action of PCP set is not being performed when QinQ is configure an interface.	112774	DM4270
<b>Aging Time</b>	There is no support to aging time configuration per interface, VLAN ID , Routed-MACs or specific MAC addresses.	-	All

Feature	Description	ID	Affected Platforms
<b>Assistant-task</b>	If there is a <b>show</b> command in the script, the next commands are not executed.	121680	All
<b>Assistant-task</b>	If script was created in Windows which use CRLF format, even DmOS converts to Unix format when import the file, the last command can not run. As workaround it is possible adding <b>!</b> character in the end of file.	-	All
<b>Backup-link</b>	It does not support Backup-link.	-	DM4618
<b>Banner</b>	On banner configuration, the <b>\</b> character (backslash) operates as an escape character. To display this character, you must insert two backslash ( <b>\\</b> ).	-	All
<b>BFD</b>	BFD sessions are not shown in DmView.	127350	All
<b>BFD</b>	In some cases, all BFD sessions may flap simultaneously.	152470	All
<b>BFD</b>	It does not support BFD.	-	DM4050 DM4250 DM461x
<b>BGP</b>	In BGP neighbors BGP with same IP address, in distinct VRF, it is not possible configure different passwords to the same neighbors.	-	All
<b>BGP</b>	Possibility of coredump if user to run commands immediately after booting the system.	113454	All
<b>BGP</b>	Lack of warning for the user that when configuring an address family in BGP will restart the BGP protocol of the equipment.	148347	All
<b>BGP</b>	BGP IPv6 neighbor accept invalid configuration <i>address-family vpnv6 unicast</i> .	154928	All
<b>Booting Process</b>	During the initialization of equipment, if a commit is executed, it might show the "Database is Locked" message until all modules are applied	-	All
<b>CFM</b>	When adding a interface that blocked by CFM to a LAG that is also blocked by CFM, it can be unblocked.	124046	All
<b>CFM</b>	Communication between MEPs may not work, being necessary to remove the CFM configuration and reapply it.	119632	All
<b>CFM</b>	CFM linktrace status remains on command <i>show oam cfm linktrace</i> after removing the CFM configuration.	136881	All
<b>CLI</b>	"show" and "commit" commands may fail if executed shortly after booting the system due of software modules initialization.	116417	All

Feature	Description	ID	Affected Platforms
CLI	<b>show configuration diff</b> command can crash requiring the user execute a CTRL+C to return to the CLI.	-	All
CLI	The <b>select</b> option of CLI filter does not work for some commands.	95478	All
Dot1q	Interfaces after dot1q refactoring are in alphabetical order and not in numerical order in the <i>show running-config</i> command.	159954	All
DHCPv4 Relay L3	It does not support IP address assignment on networks belong of L3 interfaces secondary address.	-	All
DHCPv6 Relay L3	It does no support DHCPv6 Relay L3.	-	All
DmView	Status of some protocols are not shown in DmView (Info/Config).	90961	All
DmView	DM4920 DWDM platform is not supported.	193658	DM4920
EAPS	EAPS protocol control packets can be dropped in cases of congestion, even with QoS enabled.	155888	All
EAPS	When several EAPS instances are operating, new instance activation might take several minutes to be applied after commit. In this time interval the CLI is blocked for the operator until the creation process and apply is finished.	88879	All
EAPS	It is not recommended using more than 8 EAPS instances in the same ring.	-	All
EAPS/ERPS	To have commuting times of about 50 ms with protocols ERPS and EAPS, it should be used at most 4 instances in the same ring.	-	All
ERPS	ERPS shows do not show correctly information in case of nbase-stub process restarts. To solve this it is necessary reboot the equipment.	-	All
ECMP	ECMP configuration in OSPFv2 and OSPFv3 causes BGP to use ECMP in BGP. It is not possible to disable ECMP only in BGP.	170142	All
ECMP	It is not supported ECMP in MPLS.	F1121 F2021	All
ECMP	After network convergence, traceroute may show incorrect paths.	193060	
ECMP	In OSPFv2 or OSPFv3 scenarios with ECMP, the traceroute may timeout, not correctly identifying all hops or receive answer from equipment that should not respond.	193061	

Feature	Description	ID	Affected Platforms
<b>GPON Autoprovisioning</b>	Alarm of autoprovisioning may get stuck under some configuration conditions of GPON interface.	99261	All
<b>GPON Autoprovisioning</b>	Automatic deprovisioning of ONUs is not supported.	-	All
<b>GPON Counters</b>	There is no support to VEIP counters.	-	All
<b>GPON Discovery</b>	In scenarios with ONU scalability, some ONUs that have already been provisioned may appear in the discovery.	179561	All
<b>GPON Ethernet UNI</b>	ONU profiles do not automatically create the Ethernet interfaces.	-	All
<b>GPON Firmware Update</b>	After version 4.0.2 it may occur configuration loss of GPON interfaces when upgrading from a firmware version before 4.0.2. To prevent this situation, check Compatibility between software versions section must be followed. It is also possible that third-party tools reveals incompatibility issues when using NetConf protocol to access the equipment and, in these cases, the GPON interface keys must be adjusted.	-	All
<b>GPON Flood Blocking</b>	Support to flood blocking only in Service-VLAN type N:1.	-	All
<b>GPON IP Spoofing</b>	There is no support to disabling the IP Spoofing mechanism in GPON interfaces.	-	All
<b>GPON IP Spoofing</b>	Double tag traffic will only work with allowed ip all rule applied to the service-port.	-	All
<b>GPON IP Spoofing</b>	DHCP client negotiates and receives IP address, however, the rule is not created in allowed IP list because all filters are used in equipment.	-	All
<b>GPON IP Spoofing</b>	Host connected directly to ONU bridge with service N:1 does not receive IPv6 if a <i>allowed-ip ipv6-all</i> rule is not created in the IP Spoofing filters.	173283	All
<b>GPON IP Spoofing</b>	It does not support IP Spoofing in Ethernet interfaces.	158599	DM4618
<b>GPON Line Profile</b>	There is no consistency if the user configures an invalid tcont in the line-profile, allowing to create an invalid configuration.	161379	All
<b>GPON Line Profile</b>	DHCPv6 service does not work with VLAN tagged in ONU LAN and line-profile with more than one GEM.	155121	All

Feature	Description	ID	Affected Platforms
<b>GPON L2VPN</b>	It is not supported QinQ L2VPN with service-port access.	-	DM4610-HW2 DM4615
<b>GPON Multicast</b>	IGMP is only possible in N:1 VLAN type.	-	All
<b>GPON MPLS</b>	VPWS port-based with Ethernet loop as access interface does not pass traffic.	-	All
<b>GPON MPLS</b>	PPPoE and DHCP circuit information is not sent over L2VPN with service-port access.	F1789	All
<b>GPON ONU</b>	interoperability with D-LINK ONU in bridge mode (DPN-1452DG).	F1841	All
<b>GPON ONU</b>	After several ONU firmware update executions using the parameter all, new firmware update commands are not processed until shut/no shut is performed in the PON links where the firmware update processes took place.	126539	All
<b>GPON ONU</b>	Dying Gasp is not supported for ONU SFP TEO-GNUK-S20B.	-	All
<b>GPON ONU</b>	Bridge ONUs from other vendors with service-port with <i>match vlan-id any action vlan add</i> need to use the <i>native vlan</i> configuration in the Ethernet of the ONU bridge to enable the service.	180006	All
<b>GPON ONU</b>	Possible failure in activating the Nokia ONU model G-240W-C when the ONU has different firmware versions in the Active and Standby partitions.	163162	All
<b>GPON ONU</b>	OLT overrides the dial plan configuration configured on the ONU Web.	149521	All
<b>GPON ONU</b>	After the reboot performed in the OLT firmware update, the management of ONU DM985-100 via IPHost does not return. As a workaround it is necessary to execute the <i>onu-reset</i> command.	132639	All
<b>GPON ONU</b>	Instability in services with ONU Fiberhome AN5506-02-B from version 9.0.0.	173081	DM4616
<b>GPON ONU</b>	Fiberhome AN5506-02-B ONUs take more time to stay operational.	180726	DM4616
<b>GPON ONU Discovery</b>	In scenarios with a high number of ONUs can appear invalid NS <i>show interface gpon discovered-onus</i> command.	157545	DM461x



Feature	Description	ID	Affected Platforms
<b>GPON ONU SNMP</b>	Monitoring of Ethernet ports ONU traffic by SNMP with flow greater than 38 Mbps does not work properly.	172174	All
<b>GPON ONU Status</b>	ONU Uptime is only updated every 5 minutes.	-	All
<b>GPON ONU Status</b>	Rx/TX power is only updated if the difference is upper than 0.2 dbm.	-	All
<b>GPON ONU Status</b>	<i>onu-force-status-update</i> command can not be show any update if no status has been updated and you only have uptime to update. The uptime update will not be forced.	-	All
<b>GPON ONU Status</b>	After power failure, some ONUs may have "Operational state Down" and "Primary status Active " impacting the ONU service. It is necessary to reprovision the ONU to resolve this failure.	180265 184035	All
<b>GPON ONU Status</b>	ONUs from other manufacturers may have the power value displayed with the wrong value.	132635	All
<b>GPON PON Interfaces</b>	It is not possible to execute some commands of GPON when using a range of GPON interfaces.	102236	All
<b>GPON PON Interfaces</b>	PONLINK LOS alarm generation eventually fails, without any further impact to the PONLINK, when the fiber is reconnected or other PONLINKs in the equipment. ONU LOSi alarms are generated normally during this error. The issue happens when there is an intermittent connection between the fiber and the ONT and after reconnecting the fiber to the PONLINK the system operates normally.	-	All
<b>GPON PON Interfaces</b>	Delay may occur to update PON status after link state change in scenarios with many ONUs.	147361	All
<b>GPON POTS</b>	There is no support to shutdown POTS UNI interface.	-	All
<b>GPON POTS</b>	It is not supported the ! character in sip-user-agent password command.	-	All
<b>GPON Service-Port</b>	Partial and not functional configuration of service port created using netconf in versions lower 5.6 can cause impossibility to update firmware to version 5.6 or above.	-	All
<b>GPON Service-Port</b>	Application with DHCP and ONU Router only works with service-port using replace for the same VLAN.	165374	All

Feature	Description	ID	Affected Platforms
<b>GPON Service-Port</b>	Configuration file containing service-port configured with <i>action vlan add vlan-id &lt;VLAN&gt; description &lt;DESC&gt;</i> does not apply service-port configuration. To work around it is necessary to remove the description before loading the configuration file.	183597	All
<b>GPON Service-Port</b>	It does not support interface L3 configuration in the same service port VLAN.	-	DM4618
<b>GPON SIP Profile</b>	There is no support to Call ID and Call forwarding configuration.	-	All
<b>GPON SIP Profile</b>	SIP server port is fixed as 5060.	-	All
<b>GPON SIP Profile</b>	It is allowed to configure the field display-name in a SIP agent profile with a string greater than 25 character, but the only first 25 characters are used.	108932	All
<b>GPON System</b>	Show commands related to gpon may be slow if have GPON SNMP object queries being executed at the same time as the show command.	F2017 182790	DM461x
<b>GPON SNMP</b>	Poor performance in GEM counters by SNMP.	144319	All
<b>GPON Traffic-Profile</b>	Gem-traffic-profile does not apply traffic limit in downstream for DM986-100 ONU with HGU firmware.	-	All
<b>GPON</b>	If the user does not specify the profile, all ONUs will be configured with XGSPON (10GB) profile, regardless of whether it is a GPON or XGS ONU. If it is a GPON ONU, the ONU may be Up, but it will not transmit data. The profile must match the port mode. There is no consistency preventing misconfiguration.	184045	DM4616
<b>Interfaces</b>	Commit warnings are not generated if changes are made to a range of interfaces rather than a specific interface.	99138	All
<b>Interfaces</b>	During the initialisation of DM4610 or DM4615 equipment, its interfaces may go to UP for 30 seconds even if the interfaces are in "shutdown" administratively.	-	All
<b>Interfaces</b>	It does not support cl108 FEC mode in 25 Gbps interfaces and it is recommended the use of cl74 FEC mode.	-	DM4618
<b>Interfaces</b>	The MDIX works in reverse in interfaces gigabit-ethernet 1/1/1, 1/1/5, 1/1/9, 1/1/14, 1/1/17 e 1/1/21 if it is configured as forced. MDIX works as expected when in automatic mode.	93744	DM4050 DM4250

Feature	Description	ID	Affected Platforms
<b>Interfaces</b>	The MTU value in GT and GX interfaces is actually 4 bytes smaller than the configured value when the interface is untagged.	-	DM4050 DM4250
<b>Interfaces</b>	25G interface operating at 1G speed and electrical SFP may take time to detect link down.	176787	DM4770
<b>Interfaces</b>	The inDiscard and UnknownProto counters are not supported, displaying the value zero in show and through SNMP queries.	190138	DM4920
<b>interfaces</b>	Configuration of multiple interfaces using * is not supported.	192644	DM4920
<b>Interfaces</b>	Interfaces are not disabled when deprovisioning the LC-800 Line Card, which can keep the laser transmitting. To complete the deprovisioning, the equipment must be restarted.	192978	DM4920
<b>IP Routing</b>	Hosts system can cause DoS in the equipment if a host is not available and has a lot of traffic destined for this host.	145800	All
<b>IP Routing</b>	Poor performance in convergence time when equipment have many prefixes.	158948	All
<b>IP Routing</b>	Poor performance in <i>show ip route</i> , <i>show ipv6 route</i> , <i>show ip fib brief</i> , <i>show ipv6 fib brief</i> and <i>show ip bgp prefixes</i> commands when equipment have many prefixes.	158636	All
<b>IP Routing</b>	Unable to execute "show ip ..." commands on two CLI sessions simultaneously. It is necessary to wait for the execution of the command before executing another.	M1253 M1254	All
<b>IP Routing</b>	Cannot filter prefixes using address families route-map.	180293	All
<b>L2CP</b>	L2 PDUs transparency in TLS services (service vlan type TLS) is enabled without the possibility of changing this behavior. For 1:1 and N:1 services (service vlan type 1:1 or n:1), L2 PDUs transparency is intrinsically disabled.	-	DM461x
<b>L2VPN</b>	It is not supported L2VPN configuration in interface which is MPLS access and uplink. Despite the commit being accepted, a warning is generated in this condition <i>Some MPLS VPN's have access and uplink interfaces in common. In this way those access interfaces will not be able to encapsulate MPLS traffic.</i>	135480	All

Feature	Description	ID	Affected Platforms
L2VPN	It is supported more than 8 ranges in QinQ L2VPNs with 8 ranges maximum per access interface depending on the platform. In the DM4360 and DM4370 are 20 and other platforms which supports QinQ L2VPNs are 50.	-	All
L2VPN	The <b>show mpls l2vpn counters</b> commands does not support autocomplete of the parameters.	M841	All
L2VPN	The <b>show mpls l2vpn hardware</b> command works only for VPWS.	US78815	All
L2VPN	Command <i>show mpls l2vpn vpws-group detail   name</i> keep doing pagination.	148448	All
L2VPN	During traffic convergence in network with interoperability with non Datacom equipment, the pseudowire may fail (L2VPN).	M1360	All
L2VPN	When there is a lag interface with LACP as a VPWS or VPLS access, the VPN counters are incremented by LACP control packets.	99727	All
L2VPN	Broadcast, multicast and unknown unicast packets are duplicate and counted twice in the VPN VPLS ingress counters. The duplicate packet is discard and the interface discarding counter is incremented.	-	All
L2VPN	VPN access interface counters can be incremented even when TX traffic is discarded.	121403	All
L2VPN	GMRP protocol BPDUs do not pass through VPLS, even with TLS enabled.	133639	All
L2VPN	Multicast packets encapsulated in L2VPNs are not registered in ingress counters of VPN uplink interfaces.	127464	All
L2VPN	L2VPN vlan-based and L2 circuit with QinQ enabled in the same interface access does not work.	-	All
L2VPN	LACPDUs packets are dropped on access interfaces of MPLS VPNs when the OAM EFM protocol is configured on this interface. To LACP work it is necessary remove the OAM EFM configuration in the access interface.	170840	All
L2VPN	The Backup PW uses the PW Status TLV to signal the main and backup PW information, for this reason it is necessary that neighbors have support for PW Status TLV and this TLV is enabled in L2VPN.	144471	All
L2VPN	Poor performance in <i>show mpls l2vpn</i> command, configuration GET via netconf, configuration save and configuration commit when equipment have many L2VPNs.	F1898	All

Feature	Description	ID	Affected Platforms
<b>L2VPN</b>	MPLS entries pending in hardware after configuration changes.	172788 178180	All
<b>L2VPN</b>	After changing the MTU on the L2VPN between Juniper and DmOS, it may be necessary to perform a shutdown/no shutdown operation on the access interface, if the operational status of the L2VPN is not Up.	179558	All
<b>L2VPN</b>	Double tagged packets in a port based L2VPN lose outer tag when traffic is sent to the access interface.	134999	DM4270 DM4380 DM4770 DM4775
<b>L2VPN</b>	MAC address limit is not supported in VPLS.	-	DM4270 DM4380 DM4775
<b>L3VPN</b>	It is not possible to change VRF name of an existing BGP instance.	113503	All
<b>L3VPN</b>	Eventual prefix failure in L3VPN affecting traffic after link flaps.	169360	All
<b>LAG</b>	It is only supported MC LAG in active/standby mode.	-	All
<b>LAG</b>	It is not supported MC LAG interoperability with other vendors. Other vendors are supported in equipment which have only LACP in MC LAG scenario.	-	All
<b>LAG</b>	If a equipment does not have MPLS settings and MPLS packets pass through a LAG of this equipment, the traffic will not be balanced properly.	US86449	All
<b>LAG</b>	A LAG stays up even it has less active interface than defined in minimum-active links if this setting is made only one side of the link. To operate correctly, the minimum-active links must be configured on both sides.	105313	All
<b>LAG</b>	Dynamic LAG balancing can cause traffic to be port migrating when near the full bandwidth limit of the LAG.	149885	All
<b>LAG</b>	It is not supported load balancing mode configuration.	-	DM4618
<b>LAG</b>	Dynamic load-balancing (DLB) mode is not supported.	-	DM4360 DM4370 DM461x
<b>LAG</b>	Equipment that do not support MPLS on the chipset do not consider MPLS labels on the traffic balancing.	-	DM4050 DM4250 DM4618

Feature	Description	ID	Affected Platforms
LAG	There is no LAG log when minimum-active links or maximum-active links are configured.	191769	All
LDP	There are no support to LDP Allocation mode Independent, LDP Encapsulation mode explicit-null, LDP Distribution mode On Demand, LDP Retention mode Conservative.	-	All
LDP	It is not possible the change the loopback IP address and enable the LDP protocol in a single commit.	US89105	All
LDP	When the ARP packets forwarded to the CPU is over than rate limit configured for the interface, the LDP sessions might not be established.	M43 M778	All
LDP	Link session may not go up if neighbor is restarted. To LDP work again it is necessary remove LDP container <i>config; no mpls ldp; commit</i> and configure LDP again <i>config; rollback configuration; commit</i> or restart the affected equipment	154505	All
LLDP	When a packet with an invalid TLV is received, the valid content of the packet may be discarded and no neighbor information is displayed.	121683	All
LLDP	It does not support LLDP.	-	DM4618
License	In equipment with MPLS license enabled, it could occur a failure when loading a configuration file with load override.	106007	All
License	When disabled the MPLS license with an invalid key, it will be displayed a error messaged as if the user was trying to enable the license.	-	All
License	Commit check does not work properly in MPLS license in some cases return valid instead invalid and in other cases the opposite.	136296	All
Link Flap	It does not support Link Flap detection feature.	-	DM4618
MAC Addresses	The <b>show mac-address-table</b> command presents invalid parameters in autocomplete of CLI.	91495	All
MAC Addresses	The <b>show mac-address-table type static</b> command shows all entries of MAC table.	91496	All
MAC Addresses	The repeat option was removed from <b>show mac-address-table</b> command due high CPU utilization.	140053	All
MAC Addresses	Aging time configuration above 1300 seconds is accepted in commit, but is limited in 1300 seconds in chipset.	163702	DM4618
Management Out-Band	It does not support 10 Mbps in mgmt interface. For correct operation, 100 Mbps speed or higher must be used.	-	DM4050 DM4250

Feature	Description	ID	Affected Platforms
<b>Management Out-Band</b>	Mgmt interface negotiated in 1 Gbps cause problems in equipment services. As workaround use management via L3 interface.	-	DM4050 DM4170 DM4615
<b>MPLS</b>	MPLS commands can break columns in a way that make it difficult to understand, automating commands in the CLI and making it impossible to use of filters present in the CLI.	172237	All
<b>MPLS</b>	It does not support MPLS.	-	DM4610-HW1 DM4611 DM4612 DM4616 DM4618
<b>MPLS</b>	To work the PDUs encapsulation in L2VPNs it is necessary to remove the remote-devices feature that is enabled in the default configuration. <i>configure; no remote-devices; commit.</i>	-	DM4360 DM4370
<b>Multicast</b>	It does not support IGMP.	-	DM4618
<b>OAM</b>	It does not support CFM, Ethernet OAM (EFM) and sFlow.	-	DM4618
<b>OSPF</b>	It's not possible show details of a specific OSPF neighbor. Through of <b>show ip ospf neighbor detail</b> command, it is possible to check all neighbors simultaneously.	91647	All
<b>OSPF</b>	If OSPF configuration was removed and reinserted with area index changed in a single commit, it is need to reinserted the L3 interface in OSPF configuration.	96565	All
<b>OSPF</b>	OSPF adjacencies in the same physical port cannot have different passwords.	-	All
<b>OSPF</b>	DmOS chooses inter area path instead of intra area when the equipment receives redistributed routes (external 2) in more than one area.	153689	All
<b>OSPF</b>	Redistribute static does not announce black-hole prefixes in OSPF.	159526	All
<b>OSPF</b>	OSPF export prefix-list does not work in prefix redistributed by ASBR in the ABR.	168392	All
<b>OSPF</b>	After remove the redistribute connected or static configuration in OSPF when the equipment has both redistributes configured causes prefixes to stop being announced by redistribute connected and static.	163789	All

Feature	Description	ID	Affected Platforms
<b>OSPF</b>	Removing and adding new OSPF router in the same commit creates an invalid OSPF router. To avoid the failure, it is necessary to perform the configuration in separate commits.	168219	All
<b>OSPF</b>	It does not support OSPFv3.	-	DM4618
<b>QoS</b>	Due to the size of the equipment buffers, the policer/shaper limits traffic below the configured value with high rates and TCP flow.	-	All
<b>QoS</b>	It does not support Quality of Service (QoS).	-	DM4618
<b>HQoS</b>	It does not support Hierarchical Quality of Service (HQoS).	-	DM4170 DM4270 DM4380 DM4618 DM4770
<b>QoS - Policer</b>	Policer egress counters do not work when there is an user-defined counter in the same VLAN.	-	All
<b>QoS - Policer</b>	Policer by DSCP does not match if packet have the ECN bit with value different from 0.	146120	All
<b>QoS - Policer</b>	It is not possible to limit the bandwidth of a group of VLANs in MPLS deencapsulation.	170558	All
<b>QoS - Policer</b>	The ingress Policer matching filters do not consider possible packet modifications due to ACLs rules.	-	DM4050 DM4250
<b>QoS - Policer</b>	ARP Request packets can be dropped by the Ingress Policers.	-	DM4050 DM4250
<b>QoS - Policer</b>	Drop counters in egress stage policers are not supported in DM461x platforms.	-	DM461x
<b>QoS - Policer</b>	Packets discarded by egress policers are not incremented in user-defined egress counters in DM461x platform.	-	DM461x
<b>QoS - Policer</b>	Egress Policer does not limit the packets by VLAN on an untagged interfaces.	-	DM4270 DM4380 DM4775
<b>QoS - Scheduler</b>	The weights configured in a QoS Scheduler are not respected with average flow lower than 129 Bytes.	-	DM4050 DM4250
<b>PBR</b>	It does not support PBR with ECMP.	138443	All



Feature	Description	ID	Affected Platforms
<b>PBR</b>	It does not support Policy Based Routing (PBR).	-	DM4360 DM4370 DM4611 DM4612 DM4616 DM4618
<b>Ping</b>	Ping does not for work for local address destination when it is specified a source interface.	105307	All
<b>Ping</b>	The IP address specified by the source interface parameter in the ping command is not respected when in VRFs.	120791	All
<b>Ping</b>	Ping does not for work for IPv6 local address destination in VRF.	152836	All
<b>Ping</b>	When a VRF interface is specified as a ping source, the IP address used as the source of the packet it not necessarily the address of the interface. The source interface will only specify in which VRF the ping will be executed.	-	All
<b>Ping</b>	In an equipment with VRF leaking and redistribute BGP in OSPF, it is not possible ping directly connected addresses.	123157	All
<b>Ping</b>	Inactive L3 interface continues to respond to ICMP echo request (ping) packets.	161120	All
<b>Ping</b>	In some situations the error <i>Failed to load BPF prog: 'Operation not permitted'</i> may occur in Ping IPv6 in VRF, after this error Ping does not work anymore, being necessary restart the equipment.	168676	All
<b>Provision</b>	Deprovisioning and provisioning the LC-800 Line Card leaves the Ethernet interfaces unconfigurable. If an LC-800 is deprovisioned, it is necessary to reboot the equipment for correct operation.	190941	DM4920
<b>Provision</b>	To deprovision all Line Cards it is necessary to use the <i>no provision</i> or <i>no provision chassis 1</i> command.	190137	DM4920
<b>Radius</b>	RADIUS authentication for IPv6 management is not supported.	F1618	All
<b>RDM</b>	After removing the RDM configuration from a slave equipment that had already established connection with a master RDM, show commands will keep displaying RDM informations that are not in the configuration anymore.	126618	All

Feature	Description	ID	Affected Platforms
<b>RSVP</b>	Tunnel establishment is supported only in the same OSPF area (intra-area).	-	All
<b>RSVP</b>	Tunnels may not go up if the equipment has more than one area configured in the equipment. To solve it is necessary to remove the excess areas and restart the OSPF process using the command <i>clear ospf process &lt;process_id&gt;</i> .	160143	All
<b>RSVP</b>	Slow convergence of LSPs if the equipment that has RSVP configured does not changed link to down due link down was not propagated. This behavior can occur if the L3 interface has more than one interface on the same vlan, in scenarios with technology that does not propagate the physical link down or are not configured for this.	F2002	All
<b>RSVP</b>	Tunnel in headend may not work if OSPF router-id was changed in tailend. Workaround is run <i>clear ospf process</i> command in the tailend equipment.	154174	All
<b>RSVP</b>	<i>Fast Reroute</i> and bandwidth reservation are not supported.	-	All
<b>RSVP</b>	It is not supported RSVP hello node-id.	-	All
<b>RSVP</b>	Cisco IOS XR RSVP hello interoperability with DmOS because DmOS not support RSVP hello node-id.	183958	All
<b>RSVP</b>	L2VPN configured with a tunnel that is destined for the wrong equipment causes L2VPN stays UP, but the data will be forwarded to the wrong equipment.	149350	All
<b>RSVP</b>	Poor performance in <i>show mpls traffic-eng tunnels brief</i> command when equipment have many RSVP LSPs.	-	All
<b>RSVP</b>	Timeout in <i>show mpls traffic-eng tunnels id name</i> command when equipment have many RSVP LSPs.	171842 181671	All
<b>RSVP</b>	<i>show mpls traffic-eng tunnels brief</i> command does not show all RSVP LSPs if pagination is enabled.	155125	All
<b>RSVP</b>	It is not supported MTU configuration in tunnel interface, so it is used 1500 Bytes fixed.	-	All
<b>RSVP</b>	RSVP interface tunnel MTU does not used in L2VPNs.	164084	All
<b>RSVP</b>	It does not support RSVP.	-	DM461x

Feature	Description	ID	Affected Platforms
<b>RSVP</b>	DmOS takes time to update the interface MTU on the LSPs after convergence, in some cases this time can reach minutes. Depending on the MTU of the L3 interface before convergence, the data passing through the LSPs using Path MTU Discovery will be smaller than expected until DmOS updates the MTU.	190789	All
<b>SCP - Passwords</b>	When the password has special characters, you must enter the password in single quotation marks (") or use the wizard mode (enter the command without entering the password parameter so it will be prompted and then no quotation marks are needed).	-	All
<b>Sensors</b>	Possibility of error log from sensors of equipment.	117219	All
<b>SNMP</b>	When configuring a L3 interface in VRF with <i>snmp agent listen</i> , it is possible which is allowed SNMP get using the loopback IP address if is configured in the same VRF of L3 interface.	-	All
<b>SNMP</b>	When configuring SNMP agent listen with loopback interface, the reply will be done with the loopback IP address and does not with the L3 interface IP address on which packet was sent.	-	All
<b>SNMP</b>	To get SNMP objects using IP address in VRFs it is necessary configure the <i>snmp agent listen interface</i> . If is not configured, the equipment will be reply using the global routing table if exists route in this table.	-	All
<b>SNMP</b>	If SNMP agent listen was configured in a L3/loopback interface and the IP/VRF configuration of this interface was changed, the SNMP get would not work. To workaround this issue it is necessary configure the interface before adding interface in SNMP agent listen.	125267	All
<b>SNMP</b>	The first index of the MIB object ENTITY-MIB::entPhysicalSerialNum does not return the equipment serial number.	137978	All
<b>SNMP</b>	The data type cpuCoreCoreId in MIB DMOS-SYSMON-MIB is incorrect causing Unexpected index type: 7 cpuCoreCoreId <core_id> error in Zabbix logs. The workaround is changing the cpuCoreCoreId from Unsigned8 to Unsigned32 in the DMOS-SYSMON-MIB file.	168468	All
<b>SNMP</b>	The eapsDomainName object of the MIB DMOS-EAPS is only created when configured causing failure in EAPS domain information of prototypes used in templates in Zabbix. To workaround configure eaps <eaps_id> name on all configured EAPS instances.	170864	All

Feature	Description	ID	Affected Platforms
<b>SNMP</b>	It is not possible configure the <i>snmp vacm access</i> with global VRF via DmView.	151642	All
<b>SNMP</b>	sysUpTime object counter is reset if SNMP agent is restarted.	161873	All
<b>SNMP</b>	ifAlias for GPON interface is only created after configuring a description on the GPON interface.	168099	DM461x
<b>SNMP</b>	Dying Gasp SNMP traps are not sent for SNMP targets associated to mgmt VRF or user VRFs.	US90189 US90190	DM4360 DM4370
<b>SNMP</b>	ENTITY-MIB returns triplicate slot informations.	146733	DM4610-HW2 DM4615
<b>SNMP</b>	The Ifindex returned in the ipAdEntIfIndex object does not point to any interface, meaning that tools that use SNMP are unable to correlate the IP address read with any equipment interface.	191764	All
<b>SNMP</b>	SNMP queries must use a timeout value of 100 seconds.	EP1200	DM4920
<b>SNTP</b>	Packet from SNTP server version 4 or earlier are discarded.	124339	All
<b>SSH</b>	It's possible occurs <b>Error: application timeout</b> message when to try generate SSH key. On retry the problem will not occur.	-	All
<b>SSH</b>	It is not possible connect by SSH from Cisco using old IOS version to DmOS even though DmOS has enabled legacy mode in SSH server.	-	All
<b>Static Route</b>	IPv6 static route does not work after recreating associated L3 interface.	151481	All
<b>Switching</b>	There is no support to TPID configuration.	-	All
<b>Switching</b>	The user cannot configure tagged or untagged members in VLAN ranges in a one-line CLI command.	-	All
<b>Switching</b>	Take a long time to do show, commit, save and netconf of large amount of VLAN.	-	All
<b>Switching</b>	It does not support in-Band management with a VLAN used in vlan-translate without having QinQ enabled in the interface.	-	DM4270
<b>Switching</b>	Double tagged packets do not add VLAN tag using VLAN mapping if QinQ is not enabled in interface.	-	DM4270 DM4380 DM4770

Feature	Description	ID	Affected Platforms
Switching	It does not support VLAN mapping.	-	DM4611 DM4612 DM4616 DM4618
Switching	It does not support STP, EAPS and ERPS.	-	DM4618
Syslog	Possibility of coredumps when performing <b>load override</b> command for load some specific configuration.	117306	All
Syslog	Modification in L3 interfaces used for reaching the syslog server may cause the syslog server not to work. As a workaround, it is needed to remove the syslog configuration, commit it and configured it again.	127781	All
System	Load override configuration with RSVP explicit path makes commit impossible even if the difference between the current and candidate configuration has nothing to do with RSVP.	168158	All
System	Although the option appears in the CLI, is not supported utilities after the pipe   in debug commands.	134410	All
System	PSU 200 DC does not have temperature sensors.	-	All
System	DmOS may restart if there is any equipment connected to serial sending signals with invalid characters.	162834	All
System	Some show commands may not show full output when using the " <code>  display json, xpath, etc</code> " option.	160442	All
System	RARP packets do not update the host-table causing the convergence of the VMs from software using RARP such as VMware take longer. This longer time is due to the need for a VM ARP to be the trigger for host resolution.	-	DM4618
System	The FPGA update if needs in a DmOS version will only be completed after the equipment is restarted due to power failure or removal and insertion of the power cord. Even if the update has not been completed, there will be no problem in the operation of the equipment.	-	DM4360 DM4370
System	It does not support CPU DoS Protect rate limit configuration.	-	DM4050 DM4250 DM4618

Feature	Description	ID	Affected Platforms
System	In scenarios with a high number of ONUs the CPU can get high usage generating alarm.	148808	DM4610-HW2 DM4611 DM4612 DM4616 DM4618
System	The hostname size will be limited in less than 63 characters when the equipment has DHCP Relay L2 enabled and use hostname in circuit-id format.	-	DM461x
System	Inserting the line card after the equipment is booted will cause it to be in the blocked state and shows CARD_UNINITIALIZED alarm. In order for it to become operational it will be necessary to restart the DM4618. The status of the platform and line card can be checked through the command <i>show platform</i> .	-	DM4618
System	Line card removal after equipment boot causes alarm OLT_ADAPT_FAILURE, it can also impact services running on the mainboard, for this reason it is recommended to restart the equipment after removing the line card.	166666	DM4618
System	The deprovisioning of the line card causes a failure in the SNMP get objects of IF-MIB, for this reason it is recommended to reboot the equipment after deprovisioning.	164431	DM4618
System	There are no logs about line card hardware failure.	-	DM4618
System	DM4610-HW2 equipment operating FANs with speed above necessary, causing excessive noise.	154171	DM4610
System	Memory may be allocated by internal processes due to Ethernet link flaps for an extended period of time. After the scenario is normalized, the memory will return to its initial state. It is recommended to use the Link-Flap Detection functionality to control flaps on Ethernet interfaces.	168974	All
System	<i>show interface utilization</i> is not available on this product model.	191390	DM4920
System	Using the <i>  tab</i> parameter may cause slowness in displaying information from the <i>show interface hundred-gigabit-ethernet * statistics</i> command.	190591	DM4920
System	Confirmation message for admin user password reset operation may appear incomplete. It does not affect the password reset itself.	191867	DM4920

Feature	Description	ID	Affected Platforms
<b>System</b>	EDFA interface settings are not applied when executing <i>load override</i> on a configuration file. To apply the configuration file settings, it is necessary to execute <i>load override backup.config</i> , then deprovision the EDFA Line Card ( <i>no provision chassis 1 slot &lt;4-5&gt;</i> ), apply the configuration ( <i>commit</i> ), provision the EDFA Line Card ( <i>provision chassis 1 slot &lt;4-5&gt; card-model &lt;Line Card model&gt;</i> ), apply the configuration ( <i>commit</i> ) and configure the EDFA interfaces again.	195143	DM4920
<b>TACACS+</b>	TACACS+ authentication for IPv6 management is not supported.	F1620	All
<b>TACACS+</b>	Command with more than 243 characters are not sent to the accounting server.	111614	All
<b>TACACS+</b>	Commands may not be registered in the accounting server when the command is executed and the user immediately logs out.	-	All
<b>TACACS+</b>	ERROR message generated in log when applying configuration of Banner using the multiline mode.	111616	All
<b>TACACS+</b>	Commanded reject by TACACS+ server are being registered in the accounting log.	122945	All
<b>Traceroute</b>	Equipment does not show in the traceroute path if does not exist prefix installed in route table.	162090	All
<b>Transceivers</b>	Order of transceivers is not displayed in ascending order on command <b>show interface transceivers</b> .	99257	All
<b>Transceivers</b>	Only are supported 100 Mbps optical transceivers in forced mode and only in GX interfaces.	-	All
<b>Transceivers</b>	Log of link UP is generated whenever an SFP Copper is inserted even without physical cable.	94344	All
<b>Transceivers</b>	Transceiver inventory informations are shown duplicated in DmView.	126537	All
<b>Transceivers</b>	Electrical transceiver negotiated in half-duplex shows full-duplex in DmOS.	US93493	All
<b>Transceivers</b>	When enabling negotiation in 10 Gbps interface the link will transition from UP to DOWN and then returning to UP, remaining stable.	116953	DM4050 DM4250
<b>Transceivers</b>	Removal of a SFP and insertion of another one in an interface may not be identified if it is performed in less than 3 seconds.	109496	DM4170

Feature	Description	ID	Affected Platforms
<b>Transceivers</b>	The GX interfaces of DM4610 platform do not support Copper SFPs at speeds of 10 and 100 Mbps. Some models of Copper SFPs can operate at speeds of 1 Gbps, but are not homologated by Datacom.	-	DM461x
<b>Transceivers</b>	The 10 Gbps interfaces do not support autonegotiation.	-	DM4270-48XS
<b>Transceivers</b>	The 25 Gbps interfaces do not support autonegotiation.	-	DM4770-16CX DM4618
<b>Transceivers</b>	The 100 Gbps interfaces do not support autonegotiation.	-	DM4618
<b>Transceivers</b>	10Gbps interface using 1Gbps electrical transceiver operates in negotiated mode only.	171560	DM4370 DM4611 DM4612 DM4616
<b>Transceivers</b>	There is no support for non-homologated transceivers. The use of non-approved QSFP modules may harm the DWDM infrastructure with inadequate lambda or may keep the module's laser turned on. Interfaces with non-homologated transceivers must be in shutdown. If a non-homologated module is connected to the equipment, an alarm will be displayed, which can be viewed using the <b>show alarm</b> command.	EP1200	DM4920
<b>TWAMP</b>	It takes time to run <i>show oam twamp</i> command.	135553	All
<b>TWAMP</b>	After failure in the TWAMP test-session, the SNMP objects remain with the values of the last successful test.	131279	All
<b>TWAMP</b>	Logging <b>TWAMP-SERVWAIT_TIMEOUT</b> in case of protocol communication failure. It does not impact the service.	183902	All
<b>TWAMP</b>	It does not support TWAMP.	-	DM461x
<b>VRF</b>	It does not support VRF.	-	DM4050 DM461x
<b>XGS-PON</b>	The OLT allows provisioning a maximum of 128 ONUs per PON port.	179933	DM4616
<b>XGS-PON</b>	Some ONUs from other vendors may be incompatible.	178047 174681	DM4616
<b>XGS-PON</b>	RG-Profile is not supported.	-	DM4616
<b>XGS-PON</b>	Firmware upgrade via OMCI is not supported.	-	DM4616
<b>XGS-PON</b>	TR-069 profile is not supported.	-	DM4616
<b>XGS-PON</b>	RSSI is not supported.	-	DM4616



Feature	Description	ID	Affected Platforms
<b>XGS-PON</b>	Anti-rogue is not supported on GPON ONUs.	-	DM4616
<b>XGS-PON</b>	GEM counters are not supported in the CLI and via SNMP.	177837	DM4616
<b>XGS-PON</b>	ONU DM984-42x data traffic failure when using LAN ports 2, 3 or 4.	181558	DM4616
<b>XGS-PON</b>	ONUs may have <i>Down/Active pending</i> status after UN or OLT shutdown. It is necessary to restart the ONU to return to normal operation.	182587 177543	DM4616
<b>XGS-PON</b>	If the xgspon interface mode is set to gpon, switching to xgspon and returning to gpon mode will only be applied after rebooting the OLT.	183105	DM4616
<b>XGS-PON</b>	If an ONU DM986-100 SFU with 2 gems is used, 1 gem for ethernet and a second for IPHost, the first gem must be configured for IPHost and the second gem for ethernet. Otherwise, you may lose data in the upstream direction.	176959	DM4616
<b>xSTP</b>	RSTP does not work if dot1q is not configured.	88154	All
<b>xSTP</b>	The cost of STP on interfaces by default is 20000 regardless of the interface speed, making the paths chosen by STP links with lower speed. As a workaround it is possible to change the cost in the interfaces manually as desired.	154927	All
<b>xSTP</b>	There is no support to BPDU options like: BPDU Guard and BPDU Filter.	F1131	All
<b>xSTP</b>	STP does not work with EAPS configured in the same interface.	-	All
<b>xSTP</b>	BPDU's are processed and discarded in the CPU instead of being discarded in the chipset, this can generate an overload on the equipment's CPU if a significant amount of BPDU's is received.	132238	All

## 5 Document Versions

The following table lists all documents for DmOS products. Datacom do not recommend the usage of previous versions.

### 5.1 Software Platform

Document	Version
DmOS - Quick Configuration Guide	204.4292.37
DmOS - Command Reference	204.4284.45
DmOS - Datasheet	134.4918.27
DmOS - MIB Reference	204.4381.02
DmOS - Troubleshooting Guide	204.4293.29

### 5.2 Hardware Platform

Document	Version
DM4050 - Installation Guide	204.4317.03
DM4170 - Installation Guide	204.4308.05
DM4250 - Installation Guide	204.4312.01
DM4270 - Installation Guide	204.4331.09
DM4360 - Installation Guide	204.4337.01
DM4370 - Installation Guide	204.4314.02
DM4380 - Installation Guide	204.4336.00
DM4610 - Installation Guide	204.4291.04
DM4611 - Installation Guide	204.4349.01
DM4612 - Installation Guide	204.4350.01
DM4615 - Installation Guide	204.4323.03
DM4616 - Installation Guide	204.4351.00
DM4618 - Installation Guide	204.4351.00
DM4770 - Installation Guide	204.4339.10
DM4775 - Installation Guide (Portuguese only)	204.0337.00
DM4920 - Installation Guide (Portuguese only)	204.0365.05

## Legal Note

In spite the fact that all the precautions were taken in development of the present document, DATACOM shall not be held responsible for eventual errors or omissions as well as no obligation is assumed due to damages resulting from the use of the information included in this guide. The specifications provided in this manual shall be subject to changes with no prior notification and are not acknowledged as any type of contract.

© 2023 DATACOM - All rights reserved.

## Warranty

DATACOM's products are covered by a warranty against manufacturing defects during a minimum period of 12 (twelve) months including the legal term of 90 days, as from the date of issue of the supply Nota Fiscal (Invoice).

Our warranty is standard counter warranty, this means, for exercise of the warranty, the customer should send the product to DATACOM Authorized Technical Assistance with paid freight. The return freight of the equipment will be DATACOM responsibility.

To obtain additional information, see our warranty policy in <https://www.datacom.com.br/en>.

Telephone Number: **+55 51 3933-3094**